<i>June-03-13 ∃:2</i> ,	3:17 AM				2 4		() /						7	
Item ID: Revision ID: Item Name:	D3196-4 Bar	į		A	ccept	*	N900	04 0	100)*	Setup Star Stop	I	S1* S2*	
Start Date: Required Date: Reference:	6/03/13 6/10/13	Start Qty: 6. Req'd Qty: 6.		հ* հ*			Cust Item I Customer:	D:					. 12	
Approvals:			Date: /J					nte:]	Run Star Stop		R1* R2*	
Sequence ID/ Work Center ID		Operation Description	1		Set Up/ Run Hours	s	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	-
Draw Nbr	Revi	ision Nbr	i.		. '								+	-
D3196	Rev	C	** - 4				* •	भुः						
*100 *100* Bandsaw Jeaspa Bandsaw		BAND SAW . Memo Cut bla	f ank: (0.75" x 1.50") x	34.750" long	0.00 0.00 Bar	Ro	3/06/06	·		3	Ø			_
110 *11 *11 HAAS 1 HAAS CNC vertical	machine #1	Memo 1-Mac	hine D3196-4 as per F		.0.00 f 0.00 nd Dwg D3196Ide	?O	13/06	107		2	_1_		. ·	_
¹²⁰ *12∩*		Deburn QC2- Inspect parts	off machine FAI/FAIF		0.00	80	13/06/0	i7		2.	i		: ,	
QC Quality Control		Memo	<u> </u>		0.00	V.	1-7001	,						

DQA:	A	A.	, Date:	13/06	(18	WORK ORDER NON	-C(ONFOI	RMANCE / UPDATE				DART
QA Closed:		CAL	Date:	13	6/1	Y		J. 11. O.		W	ork Order up	date only	AEROSPACE
Work Orde	er:	10	250	oZ	('	DISPOSITION			AGAINST	DE	PARTMENT	PROCESS	·
		D31		-4		Rework Scrap Use-as-is Suspected Unapproved		1	Skid-tube Crosstube Machining Small Fab noforming Finishing Large Fab Composite		╡	Water Jet d. Eng. Coor. e/Packaging Supplier	Engineering Quality Other
Root Cause		Date	Step	Qty	Desci	ription of work order update or non-conformance	l	nitial ief Eng	Action Description		Sign & Date	Verification	QC Inspector
Design Doc/Data Equip/Tooling Handling/Pre Material Operator Offset/Setup Process Supplier Training Transport Unapproved		+10 13/06/07		Ĺ	Tha	T has a dut I can't be Remove d would make it estitically right RAW makeni	(147	SURAP		PD 13/06/07	af	13/06/07
							FAI	JLT CAT	TEGORY		1		
Landii		Crimp/Kink/Ripple/Wave Burrs Cuffs Contamination Crushing Countersink Heat Treat Cut Too Short			Bend BOM/Route Broken/Damage/Defect Burrs Contamination Countersink		Grain Hardwa Inspecti Instruct	ion Incomplete/Unqualified ions Incomplete/Unclear ned/off center eled		Outside Dimo Over/Under Part Incorrec Part Lost/Mis Part Moved Positioned W Power Loss/S	tolerance t ssing	Pressure/Forced Set-up Temperature/Cure Weld Wrong Stock Pulled Other	
		Marks/Ch	atter			Drill Holes		Off-set					
		Turning Se Wave/Twi	•	e		Finish Fit/Function		ł	Calibration Sequence				

Page 2

Insp.

June-03-13 7:23:17 AM Item ID: D3196-4 Accept *N900040100* Setup Start **Revision 1D:** Item Name: Bar Start Date: 6/03/13 Start Qty: 6.00 Cust Item ID: Required Date: 6/10/13 **Req'd Qty:** 6.00 Customer: Reference: Run Process Plan: Date: Tooling: Approvals: QC: _____ Date: ____ SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Work Center ID Description **Run Hours** Code Qty **Qty** Number Stamp 130 QC8- Inspect parts - second check 0.00 and 13/06/10 *130* 0.00 Memo Quality Control 140 Chemical Conversion Coat per OSI005 4.1 0.00 b \$ 136-10 *140* HandFinish 0.00 Memo Hand Finishing 150 Grey Sandtex(Ref:4.3.5.6) per QSI005 4.3 0.00 *150* Powdercoat Memo Powder Coating _FINISH TIME:

M121279

DQA:			Date:											™ ⊃∧DT
						WORK ORDER NON	-C(ONFO	RMANCE / U	PDATE				AEROSPACE
QA Closed:			Date:								W	ork Order u	odate only	
Work Orde	er:					DISPOSITION				AGAINST	DE	PARTMENT	/PROCESS	
						Rework	1		Skid-tube	Crosstube	Г	1	Water Jet	Engineering
Part N	No.					Scrap	1		Machining	Small Fab		Pro	d. Eng. Coor.	Quality
	-					Use-as-is	1		noforming	Finishing	-	4	re/Packaging	Other
NCR N	No.					Suspected Unapproved	1		Large Fab	Composite	_	1	Supplier	
							,			·	<u> </u>		٠. ب	
Root					Desc	ription of work order update	1	Initial	Ac	tion		Sign &		
Cause		Date	Step	Qty		or non-conformance	Ch	nief Eng	Desc	ription		Date .	Verification	QC Inspector
Design							ļ							
Doc/Data	Щ					•								
Equip/Tooling	Щ						ŀ							
Handling/Pre	Щ													
Material .														
Operator							1							
Offset/Setup	Ш													
Process	Н													
Supplier	Щ						1							
Training	Н													
Transport	Н													
Unapproved			L	<u> </u>					55000	и .	-			1
1 1:-							FAI	ULI CAI	TEGORY					- "
Landii	_	ear Sending				General Bend	_]ralia/n	lro		_] 		7
	\vdash		t Concer	stric	-	BOM/Route	-	Grain	rogram		-	Outside Dim	<u> </u>	Pressure/Forced
		racks	or concer	ILIIC	-	Broken/Damage/Defect	 	Hardwa			\vdash	Over/Under	—	Set-up
	\vdash		ık/Ripple	/\\/\	-	Burrs	\vdash	ŧ		ngualified	<u> </u>	Part Incorred)	Temperature/Cure
	_	uffs	k) vibbie	/ wave	-		\vdash	1	ion Incomplete/U	•	-	Part Lost/Mi	· -	Weld
	\mathbf{H}^{\cdot}	crushing			\vdash	Contamination Countersink	\vdash	1	ions Incomplete/ ned/off center	Onclear	_	Part Moved		Wrong Stock Pulled
		leat Trea	+		\vdash	Cut Too Short	\vdash	Mislabe	•			Positioned V Power Loss/	_	Other
	\vdash		n Strip in	Tube	-	Drawing	\vdash	Misread			Ц_	Ji Owei Loss/	Juige [Tottlei
		/Jarks/Ch	٠.	· ubc		Drill Holes	\vdash	Off-set	4	•				
	_	urning S				Finish	\vdash	4	Calibration					1
	_		ist in Tub	e		Fit/Function	-	ł	Sequence					

June-03-13 7:23:17 AM Item ID: D3196-4 Accept *N900040100* Setup Start **Revision ID:** Item Name: Bar Start Qty: 6.00 **Start Date:** 6/03/13 Cust Item ID: Required Date: 6/10/13 Req'd Qty: 6.00 **Customer:** Reference: Run **Approvals:** Date: Tooling: Date: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Insp. Work Center ID Description **Run Hours** Code Qty Qty Number Stamp. 160 QC3- Inspect Part Finish 0.00 *160* 0.00 Memo Quality Control Identify as per dwg & Stock Location: 0735 170 *170* Packaging 0.00 Memo Packaging 180 QC21- Final Inspection - Work Order Release 0.00 *180* NB-04-13 QC 0.00 Memo Quality Control

DQA:		Date:											™ JVD.	T
QA Closed:		Date:			WORK ORDER NON	-C(ONFO	RMANCE / U	PDATE	١٨/	ork Order uj	odate only F	AEROSPAC) E
<u> </u>		Dute.					Ī						l	
Work Order	r:				DISPOSITION				AGAINST	DE	PARTMENT	/PROCESS		
	<u>-</u>	•		_	Rework	1		Skid-tube	Crosstube]	Water Jet	Engineering]
Part No	0.				Scrap	1		Machining	Small Fab		Pro	d. Eng. Coor.	Quality	1
					Use-as-is		Therr	noforming	Finishing		Rec/Sto	re/Packaging	Other	1
NCR No	o			_	Suspected Unapproved			Large Fab	Composite]	Supplier]
Root		-		Descr	iption of work order update	1	<u>l</u> Initial	Act	tion		Sign &			
Cause	Date	Step	Qty		or non-conformance	Ch	nief Eng	Desci	ription		Date	Verification	QC Inspector	
Design														
Doc/Data														
Equip/Tooling														
Handling/Pre									,					
Material														
Operator '														
Offset/Setup														
Process						:								
Supplier														
Training														
Transport	_													!
Unapproved														
.			_			FA	ULT CAT	TEGORY						
Landing	g Gear				General						-	_	·	
	Bending				Bend		Folio/F	rogram		L	Outside Dim	ensions	Pressure/Forced	
	Centre No	ot Conce	ntric		BOM/Route		Grain			L	Over/Under	tolerance	Set-up	
	Cracks				Broken/Damage/Defect		Hardwa	re			Part Incorred	ct [Temperature/Cure	<u>;</u>
<u>.</u>	Crimp/Kir	nk/Ripple	/Wave		Burrs		Inspect	ion Incomplete/Ur	nqualified	L	Part Lost/Mi	ssing	Weld	
	Cuffs		-		Contamination		Instruct	ions Incomplete/U	Jnclear	L	Part Moved		Wrong Stock Pulle	d
	Crushing				Countersink		Misalig	ned/off center			Positioned V	Vrong		
	Heat Trea	it			Cut Too Short		Mislabe	eled			Power Loss/	Surge	Other	
	Inspection	n Strip in	Tube		Drawing		Misread	d						
	Marks/Ch	atter			Drill Holes		Off-set							
	Turning S	equence			Finish		Out of (Calibration						
	Wave/Tw	ist in Tub	oe .		Fit/Function		Out of 9	Seauence						

H:/FORMS/Quality Assurance\approved QA/NCRWO RevH

Work Order ID: 102562

Parent Item: D3196-4

Parent Item Name: Bar

102562

D3196-4

Start Date: 6/03/13

Required Date: 6/10/13

Page 1

Start Qty: 6.00

Required Qty: 6.00

Comments:

IPP Rev: A New Issue 05-11-08 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M6061T6B0.750X01.50		Purchased	No			100	f	32.8350	2.89	18.25263			****

M6061T6B0 750X01 500

Location Loc Code Loc Qty MAT049 32.835 122753 8.835 8.72 m125771 24

**

70 13/06/06

DQA:		Date:			. WORK OBDER NON	c	ONIEOI	DNANICE / LU	DDATE					DART
QA Closed:		Date:			WORK ORDER NON	-C(ONFO	RIVIAINCE / U		Wo	ork Order up	date only		AEROSPACE
Work Orde	rder: Tt No. Date Step Qty Date Step Qty				DISPOSITION				AGAINST I	DEP	PARTMENT	PROCESS		<u> </u>
Part N	No				Rework Scrap Use-as-is Suspected Unapproved		1	Skid-tube Machining noforming Large Fab	Crosstube Small Fab Finishing Composite			Water Jet d. Eng. Coor. e/Packaging Supplier		Engineering Quality Other
Root				Desc	ription of work order update	Π	Initial	Act	ion	T	Sign &			
Cause	Date	Step	Qty		or non-conformance	Ch	nief Eng	Descr	ription		Date	Verificatio	n	QC Inspector
Design Doc/Data Equip/Tooling Handling/Pre Material Operator Offset/Setup Process Supplier Training Transport Unapproved	2										·			
						FAI	ULT CAT	EGORY						
Landi	Bendin Centre Cracks Crimp/ Cuffs Crushir	Not Conce Kink/Ripple			General Bend BOM/Route Broken/Damage/Defect Burrs Contamination Countersink		Grain Hardwa Inspecti Instruct Misalig	on Incomplete/Ur ions Incomplete/U ned/off center	· -		Outside Dimo Over/Under Part Incorrec Part Lost/Mis Part Moved Positioned W	tolerance et ssing /rong		Pressure/Forced Set-up Temperature/Cure Weld Wrong Stock Pulled
	_		7 k -	_ 	Cut Too Short	<u> </u>	Mislabe		L		Power Loss/S	ourge	<u> </u>	Other
	_		Tube	<u> </u>	Drawing	\vdash	Misread	ı		-				
		Chatter		-	Drill Holes	<u> </u>	Off-set			-				
		Sequence		\vdash	Finish Fit /Function	\vdash	1	Calibration		-		<u> </u>		
	[Wave/	Twist in Tul	oe .	[Fit/Function	1	[Out of S	equence						

H:/FORMS/Quality Assurance\approved QA/NCRWO RevH


DART AEROSPACE LTD	Work Order:	102562
Description: Bar	Part Number:	D3196-4
Inspection Dwg: D3196 Rev: C		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
34.625	+/-0.010	34.625	0		MTape	P40-11
33.650	+/-0.010	33,650	/		HASS2	
16.639	+/-0.010	16.639	1		મ	
0.488	+/-0.010	.486	/		JERN	P40-12
0.962	+/-0.005	.960	1		· ·	~
0.464	+/-0.010	.460			f.	• 1
0.504	+/-0.010	. 501	~		15	*4
Ø0.344	+0.006/-0.001	. 343	30		11	.1
Ø0.660 x 100°	+0.008/-0.001 x 0.5°	.660	/		J.	1.
0.512	+/-0.005	.510	1		6.	, n
0.060 x 45°	+/-0.010 x 0.5°	.060	V		l.«	7
4.750	+/-0.010	4.750	/		l.	l,
12.531	+/-0.010	12531			16	٦
16.627	+/-0.010	16.627			4	ኅ
21.844	<u>+/-</u> 0.010	21 844			Į	1
29.625	+/-0.010	29.625	/		+(·,
0.250	+/-0.010	.250			• 4	•
1.000	+/-0.010	1,000			1<	~:
R0.125	+/-0.010	-125	/		Ral G	
0.987	+/-0.010	-988			VERN	140-12


Measured by:	Audited by:	and	Preliminary Approval:	
Date: 13/06/07	Date:	13/06/10	Date:	

Rev	Date	Change	Revised by	Approved
<u> </u>	04.04.20	New Issue	KJ/RF	
В	06.10.24	Dwg Rev updated	KJ/JLM .	7/
С	11.06.21	Dwg Rev updated	KJ dely	.///












102562

DRAWING NO	D. TITLE		REV. C	DART AEF	ROSPACE LT	D.E.O. NO.		SHEE	Ť NO.	SCALE
D3196	BAR				RING ORDER		-1		2 OF 2	NTS
DRAWN	AJ5	CHECKED	_	MFG. APPR.	91	APPROVED	10	DE APPR.	#	
DATE	08.08.27	DATE (8.08.28	DATE	08.08.29	DATE	08.08.29	DATE	08.09.04	








SECTION D-D

SECTION F-F



NOTE: THIS CHANGE HAS BEEN DONE TO CLARIFY SLOT DIMENSIONS ONLY. NO CHANGES HAVE BEEN MADE TO THE PARTS SEE NCR 08-051 FOR FURTHER INFORMATION ALL OTHER INFORMATION REMAINS UNCHANGED

COPYRIGHT © 2003 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT I

NOT TO BE USED FOR ANY PURPOSE OR COPED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT

WRITTEN PERMISSION FROM DARK AEROSPACE LTD.